

# Research Garage Group Ltd

Accident Repair Centre  
Hilary Road  
Camphill Industrial Estate  
Nuneaton  
Warwickshire  
CV10 9AD

TEL: 024 7638 5757  
FAX: 024 7635 0460  
www.researchgaragegroup.co.uk  
info@resgarage.co.uk

Company No: 1021262  
VAT No: 113 7792 67

MR J TWEED  
10 ELLIOT MEWS  
STOCKINGFORD  
NUNEATON  
CV109HA

**Estimate :** A10020270  
**Date :** 01 Apr 2010  
**Claim Nr :** TWEDD  
**Cont. Tel :** 07834584333  
**Auda'x Ref:** A0020270

## ESTIMATE

<b>Manufacturer</b>	FIAT	<b>Mileage</b>	0
<b>Model</b>	BARCETTA	<b>Colour Code</b>	MET BLACK
<b>Vehicle Reg</b>	N466VPB	<b>V.I.N.</b>	ZFA18300000016650

**Tyre Depth mm : NSF : OSF : NSR : OSR : SP :**

### Remove the Following:

VEHICLE PREPARATION TIME	R + R FRONT BUMPER
R + R FRONT BADGE	R + R L/F FOG LAMP LATCH COVER
R + R R/F FOG LAMP LATCH COVER	R + R L/DUAL HEADLAMP
(BUMPER REMOVED)	R + R R/DUAL HEADLAMP
(BUMPER REMOVED)	R + R L/SIDE FLASHER LAMP
R + R R/SIDE FLASHER LAMP	R + R LEFT DOOR TRIM
R + R L OUTER DOOR HANDLE	(DOOR TRIM REMOVED)
R + R L/OUTER WINDOW CHANNEL MOULDING	R + R L/DOOR MIRROR
(DOOR TRIM REMOVED)	R + R RIGHT DOOR TRIM
R + R RIGHT OUTER DOOR HANDLE	(DOOR TRIM REMOVED)
R + R R/OUTER WINDOW CHANNEL MOULDING	R + R R/DOOR MIRROR
(DOOR TRIM REMOVED)	R + R FOLDING ROOF COVER LID
R + R REAR BUMPER	INCLUDES: R + R NUMBER PLATE LAMPS,
REVERSING LAMP AND REAR FOG LAMP	R + R LEFT TAILLAMP
R + R RIGHT TAILLAMP	R + R L/R INDICATOR
R + R R/R INDICATOR	R + R BOOT LID
R + R REAR BADGE	R + R REAR NUMBER PLATE
R + R FRONT WASHER NOZZLE/S	

### Panelwork

REPAIR LEFT DOOR

### Paint Preparation

FRONT BUMPER REPAIR PAINT PLASTIC	BONNET REPAIR PAINTING <50%
L/F WING REPAIR PAINTING <50%	R/F WING REPAIR PAINTING <50%
UPP OUT FRONT PANEL REPAIR PAINTING <50%	WINDSCREEN FRAME REPAIR PAINTING <50%

Continued...

# Research Garage Group Ltd

Accident Repair Centre  
Hilary Road  
Camphill Industrial Estate  
Nuneaton  
Warwickshire  
CV10 9AD

TEL: 024 7638 5757  
FAX: 024 7635 0460  
www.researchgaragegroup.co.uk  
info@resgarage.co.uk

Company No: 1021262  
VAT No: 113 7792 67

## Paint Preparation

LEFT DOOR REPAIR PAINTING <50%	RIGHT DOOR REPAIR PAINTING <50%
L/OUTER SILL PANEL REPAIR PAINTING <50%	R/OUTER SILL PANEL REPAIR PAINTING <50%
REAR BUMPER REPAIR PAINT PLASTIC	REAR UPPER END PANELREPAIR PAINTING <50%
BOOTLID REPAIR PAINTING <50%	L/R WING REPAIR PAINTING <50%
R/R WING REPAIR PAINTING <50%	FOLDING ROOF COVER REPAIR PAINTING <50%
L/DOOR MIRROR SURFACE PAINT PLAST.	R/DOOR MIRROR SURFACE PAINT PLAST.
Paint preparation	

## Paint Work

FRONT BUMPER REPAIR PAINT PLASTIC	BONNET REPAIR PAINTING <50%
L/F WING REPAIR PAINTING <50%	R/F WING REPAIR PAINTING <50%
UPP OUT FRONT PANEL REPAIR PAINTING <50%	WINDSCREEN FRAME REPAIR PAINTING <50%
LEFT DOOR REPAIR PAINTING <50%	RIGHT DOOR REPAIR PAINTING <50%
L/OUTER SILL PANEL REPAIR PAINTING <50%	R/OUTER SILL PANEL REPAIR PAINTING <50%
REAR BUMPER REPAIR PAINT PLASTIC	REAR UPPER END PANELREPAIR PAINTING <50%
BOOTLID REPAIR PAINTING <50%	L/R WING REPAIR PAINTING <50%
R/R WING REPAIR PAINTING <50%	FOLDING ROOF COVER REPAIR PAINTING <50%
L/DOOR MIRROR SURFACE PAINT PLAST.	R/DOOR MIRROR SURFACE PAINT PLAST.
Paint preparation	

## Denib and Polish

FRONT BUMPER REPAIR PAINT PLASTIC	BONNET REPAIR PAINTING <50%
L/F WING REPAIR PAINTING <50%	R/F WING REPAIR PAINTING <50%
UPP OUT FRONT PANEL REPAIR PAINTING <50%	WINDSCREEN FRAME REPAIR PAINTING <50%
LEFT DOOR REPAIR PAINTING <50%	RIGHT DOOR REPAIR PAINTING <50%
L/OUTER SILL PANEL REPAIR PAINTING <50%	R/OUTER SILL PANEL REPAIR PAINTING <50%
REAR BUMPER REPAIR PAINT PLASTIC	REAR UPPER END PANELREPAIR PAINTING <50%
BOOTLID REPAIR PAINTING <50%	L/R WING REPAIR PAINTING <50%
R/R WING REPAIR PAINTING <50%	FOLDING ROOF COVER REPAIR PAINTING <50%
L/DOOR MIRROR SURFACE PAINT PLAST.	R/DOOR MIRROR SURFACE PAINT PLAST.
Paint preparation	

## Refit the Following:

VEHICLE PREPARATION TIME	R + R FRONT BUMPER
R + R FRONT BADGE	R + R L/F FOG LAMP LATCH COVER
R + R R/F FOG LAMP LATCH COVER (BUMPER REMOVED)	R + R L/DUAL HEADLAMP
(BUMPER REMOVED)	R + R R/DUAL HEADLAMP
R + R R/SIDE FLASHER LAMP	R + R L/SIDE FLASHER LAMP
R + R L OUTER DOOR HANDLE	R + R LEFT DOOR TRIM (DOOR TRIM REMOVED)
R + R L/OUTER WINDOW CHANNEL MOULDING (DOOR TRIM REMOVED)	R + R L/DOOR MIRROR
R + R RIGHT OUTER DOOR HANDLE	R + R RIGHT DOOR TRIM (DOOR TRIM REMOVED)
R + R R/OUTER WINDOW CHANNEL MOULDING	R + R R/DOOR MIRROR

Continued...

# Research Garage Group Ltd

Accident Repair Centre  
Hilary Road  
Camphill Industrial Estate  
Nuneaton  
Warwickshire  
CV10 9AD

TEL: 024 7638 5757  
FAX: 024 7635 0460  
www.researchgaragegroup.co.uk  
info@resgarage.co.uk

Company No: 1021262  
VAT No: 113 7792 67

## Refit the Following:

(DOOR TRIM REMOVED)	R + R FOLDING ROOF COVER LID
R + R REAR BUMPER	INCLUDES: R + R NUMBER PLATE LAMPS,
REVERSING LAMP AND REAR FOG LAMP	R + R LEFT TAILLAMP
R + R RIGHT TAILLAMP	R + R L/R INDICATOR
R + R R/R INDICATOR	R + R BOOT LID
R + R REAR BADGE	R + R REAR NUMBER PLATE
R + R FRONT WASHER NOZZLE/S	

## Valeting and QA Checks

CHECK AND QUALITY CONTROL	CHECK FOR OVERSPRAY
CHECK AND VALET VEHICLE	

Total Labour Cost(33.05Hrs)	£859.30
Total Parts Cost	£0.00
PAINT & MATERIALS	£910.13
Nett Total	£1769.43
VAT	£309.65

Total	£2079.08
-------	----------

This estimate is valid for 3 Months, any hidden damage found upon dismantling will be subject to a further estimate.