

Customer Name & Address		Product	Price
1	Mr. John Doe	100g of Product A	1.50
2	Mr. John Doe	50g of Product B	0.75
3	Mr. John Doe	25g of Product C	0.37
4	Mr. John Doe	12.5g of Product D	0.19
5	Mr. John Doe	6.25g of Product E	0.09
6	Mr. John Doe	3.125g of Product F	0.05
7	Mr. John Doe	1.5625g of Product G	0.02
8	Mr. John Doe	0.78125g of Product H	0.01
9	Mr. John Doe	0.390625g of Product I	0.00
10	Mr. John Doe	0.1953125g of Product J	0.00

You were served by: Michelle Gillon

Account No.	Document Number	Date & Tax Point	Repair Date	Order Number	
C0002	43505454	07/07/2009			
Make & Model	Chassis No.	Engine No.	Mileage	Time	Page
edici 1.9 m-jet Eleganza		5132823	45983	14:53	1
Reference No.	Reg No.	Reg Date.	VS# No.	W.I.P. No.	Job No.
		14/12/2006		W 24395	5363

MILL LANE SERVICE DEPARTMENT
THANKYOU FOR YOUR CUSTOM

	Description of Goods / Services	Qty.	Unit Price	Unit Des.	Net Total	V
A LAB	Reset oil degregation light.				35.00	S

E. & O. E.		V	Rate	Service/Goods	V.A.T.		
Parts	0.00	S	15.00	35.00	5.25	Net	35.00
Surcharge	0.00					V.A.T.	5.25
Labour	35.00					Total	40.25
Sublet	0.00					Paid	0.00
Menus	0.00					Owing	40.25



Report duplicated

S/N 42/06 020344 - 93654-69O4T-AE4EE

Customer's Name:

Vehicle: FIAT SEDICI 1.9 MJET 8V Chassis: km: 45983

Control Unit Test: Bosch Diesel Injection EDC16C39 CF4/EOBD SZK (eng. 1.9)

Date: 07/07/2009 Time: 14:24:25

ISO code: FD 86 54 85 31

HW number: 0281012992

HW version: 00

SW number: 1037379665

SW version: 3241

FIAT drawing: 33920-79JQ0

Homologation number: 079JQ

Programming date: 12/07/2006

Parameters

Engine speed 851 Rpm

Accelerator pedal 0 %

Air mass measured 466 mg/injec.

Total Quantity Diesel 4.4 mm3/inject

Diesel press. measured 272 bar

Vehicle version with DPF

Overboost press. measured 1014 mbar

Engine startup Allowed

Maximum engine speed 0 Rpm

Max. eng. speed counter 0 msec.

Number of overrevs 0

Errors detected by the Control unit

U1601 - C-CAN line error Intermittent

Mute

P0500 - Vehicle speed signal (CAN) Intermittent

Signal not valid

Active Diagnoses

Component activation Test results

Error deletion Performed

Oil change (only for version with DPF) Performed

Operator's signature