


NUOVA BRAVO 1.4 16v DOOR MIRROR COVER (ONE), LEFT OR RIGHT - R.R
7005R37



 Removing ([Refitting](#) )

Op. 7005R35 DOOR MIRROR REFLECTOR (ONE), LEFT OR RIGHT - R.R

Op. 7005R36 DOOR MIRROR ADJUSTMENT MOTOR (ONE), LEFT OR RIGHT - R.R

1. Remove the cover (1a), releasing the retainers (1b).

 Refitting ([Removing](#) )

- Check that the cover is not damaged.
- Position the cover and attach the retainers.

Op. 7005R36 DOOR MIRROR ADJUSTMENT MOTOR (ONE), LEFT OR RIGHT - R.R

Op. 7005R35 DOOR MIRROR REFLECTOR (ONE), LEFT OR RIGHT - R.R