

Test report of vehicle trouble diagnosis

The Report is created by TOPDON

Repair Shop

Shop Name:Trusty Spanners

Address:SG15PZ

Telephone:7861284713

SN:988975612803

Test Time:11/14/2023 12:02

Vehicle Information

Make:FIAT

Model:CINQUECENTO/500/595

Year:2007

VIN:ZFA3120000J070236

Mileage:61722miles

Vehicle Software Version:V10.50

Inspection Result

ECM (Engine Control Module) 5 problems exist

1.P1300-55 Phonic Wheel Missed Self Learning - Not Configured

2.U0422-81 FPS Strategy Not Valid Data From BCM - Invalid Serial Data Received

3.P0638-61 Motorized Throttle Valve - Signal Calculation Failure

4.P0443-11 Purge Canister Valve - Circuit Short To Ground

5.P1684-94 Motorized Throttle Self Learning (Low Battery) - Unexpected Operation