

Scan vehicle for available modules and check each module for errors...

ABS

Bosch ABS 8 VDC

ISO Code: 25 86 32 07 B9

Hardware number: 0265951740 - Ver: 00

Software number: BB 66990 - Ver: 0300

Errors found:

C1117 - Steering angle sensor (NGE)

Electric Steering

TRW Electric Power Steering (3)

ISO Code: 52 80 8C 04 37

Hardware number: A0035889 - Ver: 01

Software number: NJC11686 - Ver: 0A03

Airbag

Continental Airbag (PROXI)

ISO Code: EA 07 3D 8A 0D

Hardware number: A2C53437923 - Ver: 11

Software number: 40400202106 - Ver: 0000

Body

Body Computer Marelli (198)

ISO Code: BF 83 0D 0D 31

Hardware number: BC198T.0200 - Ver: 02

Software number: 04440003810 - Ver: 0800

Errors found:

B1046 - Inertia (FIS) switch command Engine Control Node

B10AA - PROXI configuration control

B1015 - Number plate lights

B1009 - Side lights on left side or front left

U1602 - CAN line error

Dashboard

Instrument Panel Marelli

ISO Code: 32 83 AD 86 3D

Hardware number: 50011180001 - Ver: 01

Software number: 04000011126 - Ver: 0225

Dashboard

Convergence Marelli/Microsoft (Blue&Me)

ISO Code: B5 83 8A 85 1C

Hardware number: 05035505871 - Ver: 00

Software number: 05.003.7152 - Ver: 7152

VEHICLE SCAN REPORT

Scanning ...

ABS

Bosch ABS 8 VDC

ISO Code: 25 86 32 07 B9

Hardware number: 0265951740 - Ver: 00

Software number: BB 66990 - Ver: 0300

Errors found:

C1117 - Steering angle sensor (NGE)

Electric Steering

vehicle diagnostic report

13/08/2024 18:02:57

TRW Electric Power Steering (3)

ISO Code: 52 80 8C 04 37
Hardware number: A0035889 - Ver: 01
Software number: NJC11686 - Ver: 0A03

Airbag

Continental Airbag (PROXI)

ISO Code: EA 07 3D 8A 0D
Hardware number: A2C53437923 - Ver: 11
Software number: 40400202106 - Ver: 0000

Body

Body Computer Marelli (198)

ISO Code: BF 83 0D 0D 31
Hardware number: BC198T.0200 - Ver: 02
Software number: 04440003810 - Ver: 0800

Errors found:

B1046 - Inertia (FIS) switch command Engine Control Node

B10AA - PROXI configuration control

B1015 - Number plate lights

B1009 - Side lights on left side or front left

U1602 - CAN line error

Dashboard

Instrument Panel Marelli

ISO Code: 32 83 AD 86 3D
Hardware number: 50011180001 - Ver: 01
Software number: 04000011126 - Ver: 0225

Dashboard

Convergence Marelli/Microsoft (Blue&Me)

ISO Code: B5 83 8A 85 1C
Hardware number: 05035505871 - Ver: 00
Software number: 05.003.7152 - Ver: 7152

COMPLETED

VEHICLE MAKE: Fiat
VEHICLE MODEL: Bravo
VEHICLE YEAR: 2014

SENDING DIAGNOSTIC REPORT ...