



## NUOVA BRAVO 1.4 16v REAR WIPER MOTOR - R+R 5050C42



 Removing ( [Refitting](#)  )

**Op. 5050C34 REAR WIPER ARM WITH BLADE - R+R**

**Op. 7015A05 TAILGATE LOWER INTERIOR PANEL-R R**

1. Disconnect the electrical connection for the rear windscreen wiper motor.

	Description	Connector
1	REAR WIPER MOTOR	<a href="#">See N016 REAR WINDOW WIPER MOTOR</a>

2. Remove the rivets using a drill.

3. Remove the rear windscreen wiper motor.

- If necessary, working from the outside of the rearscreen, remove the seal for the opening for the glass and check that it is intact.

 Refitting ( [Removing](#)  )

- Check that the rear windscreen wiper motor is not damaged.

- If removed, position the seal on the glass opening.

- Position the rear windscreen wiper motor and apply the rivets.

- Connect the electrical connection for the rear windscreen wiper motor.

**Op. 7015A05 TAILGATE LOWER INTERIOR PANEL-R R**

**Op. 5050C34 REAR WIPER ARM WITH BLADE - R+R**